

# **ELEVATOR SAFETY BOARD AGENDA**

#### June 18, 2025 9:30 am In Person Available by Webex. (A portion of this meeting will be closed, pursuant to RSMo 610.021(3))

- I. OPEN AND WELCOME
- II. APPROVAL OF April 24, 2025 MINUTES

# III. VARIANCE REQUESTS AS SHOWN BELOW

	STATE ID	LOCATION ADDRESS	VARIANCE	CODE SECTION
1	7623	105 E Ash St, Columbia, MO 65203	Variance request for installed safety beam replacing old part, not compatible with the existing code	A17.1-2016 8.6.4.19.6 Firefighters' Emergency Operation and MO Min 11 CSR-5.065 (S) Fire Service
2	8591	12284 De Paul Dr, Bridgeton, MO 63044	The variance request is to remove battery backup due to having emergency/standby power.	ASME A17.1-2016 - 8.6.1.7.5
3	9133	4970 Oakland Ave, St. Louis, MO 63110	The variance request is to remove the battery backup because it is not working properly and may not work if repaired.	ASME A17.1-2016 – 8.6.1.7.5
4	20115	2800 E Rock Haven Rd, Harrisonville, MO 64701	The variance request is for the emergency/standby indicator light to not be there, per code, it should be	A17.1-2005 2.27.2 Emergency or Standby Power System
5	21349	12284 De Paul Dr, Bridgeton, MO 63044	The variance request is to remove battery backup due to having emergency/standby power.	ASME A17.1-2016 – 8.6.1.7.5
6	21350	12284 De Paul Dr, Bridgeton, MO 63044	The variance request is to remove battery backup due to having emergency/standby power.	ASME A17.1-2016 – 8.6.1.7.5
7	24402	100 N Main St, Paris, MO 65275	Variance request to have a residential elevator in a commercial application	MEMORANDUM 015-1 Residential Elevators in Commercial Use
8	27039	1575 Bryan Rd, Dardenne Prairie, MO 63366	24/7 Communications required per IBC code	IBC 2018/ASME 2019 Section 2.27.1

9	27040	1575 Bryan Rd, Dardenne Prairie, MO 63366	24/7 Communications required per IBC code	IBC 2018/ASME 2019 Section 2.27.1
10	27041	1575 Bryan Rd, Dardenne Prairie, MO 63366	24/7 Communications required per IBC code	IBC 2018/ASME 2019 Section 2.27.1 and A17.1-2019 2.2.2.5
11	27042	4140 Forest Park Ave, St. Louis, MO 63110	24/7 Communications required per IBC code and sump pump	IBC 2018/ASME 2019 Section 2.27.1 and A17.1-2019 2.2.2.5
12	27043	4140 Forest Park Ave, St. Louis, MO 63110	24/7 Communications required per IBC code and sump pump	IBC 2018/ASME 2019 Section 2.27.1 and A17.1- 2019 2.2.2.5
13	27044	4140 Forest Park Ave, St. Louis, MO 63110	24/7 Communications required per IBC code and sump pump	IBC 2018/ASME 2019 Section 2.27.1 and A17.1-2019 2.2.2.5
14	27045	4140 Forest Park Ave, St. Louis, MO 63110	24/7 Communications required per IBC code and sump pump	IBC 2018/ASME 2019 Section 2.27.1 and A17.1-2019 2.2.2.5
15	27084	120 S Central Ave, St. Louis, MO 63105	24/7 Communications required per IBC code	IBC 2018/ASME 2019 Section 2.27.1
16	27085	120 S Central Ave, St. Louis, MO 63105	24/7 Communications required per IBC code	IBC 2018/ASME 2019 Section 2.27.1
17	27094	6600 NW Brush Creek Pkwy, Parkville, MO 64152	24/7 Communications required per IBC code	IBC 2018/ASME 2019 Section 2.27.1
18	27143	210 N Owensby St, La Plata, MO 63549	Variance request for platform lift installation in existing residential shaft, the platform does not meet specs.	A18.1-2014 2.6.5
19	667	204 S 9th St, Columbia, MO 65201	Variance request for non-elevator- related electrical equipment to remain in the machine room/without using a divider. Modernization scheduled.	11 CSR 40-5.065 Missouri Minimum Safety Codes for Existing Elevator Equipment (H)2
20	363	3333 S NATIONAL AVE, SPRINGFIELD, MO 65807	A variance request is being made for non-elevator-related electrical equipment to remain in the machine room without using a divider. Modernization is scheduled.	11 CSR 40-5.065 Missouri Minimum Safety Codes for Existing Elevator Equipment (H)2

# IV. INSPECTOR LICENSE

a. Celso Sebastian Febles Jr.- Veteran Elevator Inspection Services, LLC

- b. Nathan J. Helminger- Maverick Elevator Inspections, LLC
- c. Maksym Kolosha- Elevator Safety Inspection Services Inc

#### V. CONTRACTOR LICENSE

- a. D&D Elevators Inc
  - i. Missing No Tax Due documentation from the Missouri Department of Revenue.
- b. Cardinal Hoist, LLC

#### VI. MECHANIC LICENSE

- a. Donald Moncler was approved.
- b. Joshua Cobb Alimak Group
- VII. New Cote Brilliant Church of God (#23730)
  - a. The Elevator Safety Board has denied the variance for this location at the March 13, 2025, meeting.
  - b. If New Cote allows inspectors to complete the variance process, will the Board entertain another variance application?
  - c. If not (b), this elevator is still in operation, and a discussion about red tagging the unit needs to take place.

# VIII. CHIEF'S REPORT

- a. Code update meeting for 2025.
  - i. There are no requirements in the rules for the Elevator Safety Unit to hold code update meetings.
  - ii. There is a requirement for Inspectors to attend at least one code update meeting per year.
  - iii. There are no new code updates to present.
  - iv. What needs to be done to satisfy all requirements?
- b. Mechanic Application Form and Rules
  - i. AND vs. OR for training/certification requirements.
  - ii. Removing the insurance requirement from the form.
- c. Camdenton residential elevator
  - i. New installation in 2024 of residential elevator in commercial setting.
    - 1. Installed without an installation permit.
    - 2. Installed by a non-licensed contractor.
    - 3. Do we register the elevator and have them apply for a variance, or direct the removal of equipment and installation of commercial equipment?
- d. Fee update
  - i. June 12, 2025, meeting with the Governor's Office and the DPS Director's Office.
- IX. (CLOSED Meeting) Inspection of New Cote Brilliant Church of God (#23730)
- X. Adjournment